

FLASHLUBE CATCH CAN PRO KITS



MAKE	MODEL	APPLICATION	YEAR	KIT NO
Ford	Ranger PX	P4AT 2.2L (Electronic Steering, No Power Steering Reservoir)	09/11-08/18	FCCKT07
Ford	Ranger PX-PX2-PX3	P5AT 3.2L (Electronic Steering, No Power Steering Reservoir)	09/11-08/18	FCCKT07
Ford	Ranger PX	P4AT 2.2L (Power Steering Reservoir on Front Panel)	09/11-08/18	FCCKT07PS
Ford	Ranger PX-PX2-PX3	P5AT 3.2L (Power Steering Reservoir on Front Panel)	09/11-08/18	FCCKT07PS
Holden	Colorado	RG1,2,3 L4 2.8L Auto/Manual	06/2012-	FCCKT10
Holden	Colorado 7	RG1,2,3 L4 2.8L Auto/Manual	06/2012-	FCCKT10
Holden	Trailblazer	RG1,2,3 L4 2.8L Auto/Manual	06/2012-	FCCKT10
Isuzu	D-Max	TFR,TF585 4JJ1TC 3.0L (Will Not Fit 3.0L Prior to 2012 or after 2/17, Identified by Orange Hose)	2012-01/17	FCCKT11
Isuzu	D-Max	TFR,TF585,86 DT4 3.0L Auto/Manual (Orange Intercooler Hose)	02/2017-	FCCKT19
Isuzu	MU-X	UCR,UCS85 4JJ1TC 3.0L (Will Not Fit 3.0L Prior to 2012 or after 2/17, Identified by Orange Hose)	2012-01/17	FCCKT11
Isuzu	MU-X	UCR,UCS85 DT4 3.0L Auto/Manual (Orange Intercooler Hose)	02/2017-	FCCKT19
Mazda	BT50	P4AT 2.2L (Electronic Steering, No Power Steering Reservoir)	10/2011-	FCCKT07
Mazda	BT50	P5AT 3.2L (Electronic Steering, No Power Steering Reservoir)	10/2011-	FCCKT07
Mazda	BT50	P4AT 2.2L (Power Steering Reservoir on Front Panel)	10/2011-	FCCKT07PS
Mazda	BT50	P5AT 3.2L (Power Steering Reservoir on Front Panel)	10/2011-	FCCKT07PS
Mitsubishi	Challenger	PB,PC 4D56T 2.5L	12/2009-	FCCKT14
Mitsubishi	Pajero	NS,NT,NW,NX remove 4M4I 3.2L (Will not suit TJM Snorkel)	10/06-2017	FCCKT13
Mitsubishi	Pajero Sport	QE 4N15T 2.4L	01/2015-	FCCKT18
Mitsubishi	Triton	ML 4M41T 3.2L	2006-2009	FCCKT34
Mitsubishi	Triton	MN 4D56T 2.5L	2009-2015	FCCKT14
Mitsubishi	Triton	MQ,MR 4N15T 2.4L	01/2015-	FCCKT18
Nissan	Navara	D22YD25T 2.5L (With Intercooler)	01/2008-	FCCKT27
Nissan	Navara	D23 NP300YS23DDT 2.3L (Will Not Suit Vehicle with Snorkel)	05/2015-	FCCKT30
Nissan	Navara	D40MYD25T 2.5L (Spain,Thailand Built without Air Sensor)	2006-2014	FCCKT05
Nissan	Navara	D40T YD25T 2.5L (Thailand,Spain Built without Air Sensor) remove	2006-2013	FCCKT05
Nissan	Navara	D40T YD25T 2.5L (Thailand, Spain Built with Air Sensor - Will not suit Dual Hump airbox)	2010-2014	FCCKT25
Nissan	Patrol	GUY61 ZD30DDT1 3.0L (Dual Battery, Breather Centre of Valve Cover, Not Common Rail)	09/2007- 2016	FCCKT12
Toyota	Fortuner	GUN156 1GDFTV 2.8L	07/2015-	FCCKT29
Toyota	Hilux	KUN26 1KDFTV 3.0L (Connects to Breather on Intake Air Pipe)	2005-	FCCKT36
Toyota	Hilux	KUN26 1KDFTV 3.0L (ABS Model remove Without VSC Fitted)	04/05-05/15	FCCKT23
Toyota	Hilux	KUN26 1KDFTV 3.0L (With VSC Fitted)	04/05-05/15	FCCKT23V
Toyota	Hilux	GUN126,136 1GDFTV 2.8L	05/2015-	FCCKT29
Toyota	Landcruiser	HDJ100 1HDT 4.2L (With Factory Turbo)	01/1998-	FCCKT35
Toyota	Landcruiser	VDJ7# 1VDFTV 4.5L (No Fuse Box Located Between Battery & Radiator)	01/2007-	FCCKT20
Toyota	Landcruiser	VDJ200 1VDFTV 4.5L	09/07-	FCCKT22
Toyota	Prado	GDJ150 1GDFTV 2.8L	06/2015-	FCCKT28
Toyota	Prado	KDJ120 1KDFTV 3.0L	09/2002-	FCCKT03
Toyota	Prado	KDJ150 1KDFTV 3.0L	08/2009-2015	FCCKT21
Volkswagen	Amarok	14 16V 2.0L 120-130kW	2010-2018	FCCKT15



flashlube.com